

**LIST OF SCRAP LOTS FOR E-AUCTION NO. ASL/MCL/DISPOSAL/20-21/01**  
**DATED 07/07/2020**

| Sl No | MCL Control no.  | Survey off Report no                    | Material description   | Location                  | Unit of Measures | QTY . |
|-------|------------------|---|--|---------------------------|------------------|-------|
| 1     | MCL/HQ/01(19-20) | SBP/MCL/HQ/Admn/18-19/01<br>Dt.24.04.19 | Scrap details arising out of the vehicles no.OR-15A-1680 Veh.Type – Deregistered Ambassador Car, Engine no.6EH092675, Chassis no.III648442, Year of manufacture-1992   | Jagrutivihar MCL HQ Burla | Nos              | 1     |
| 2     | MCL/HQ/02(19-20) | SBP/MCL/HQ/Admn/18-19/02<br>Dt.24.04.19 | Scrap details arising out of the vehicles no.OR-15B-2076 Veh.Type - Deregistered Ambassador Car, Engine no.3ELHU035332, Chassis no AHU721027, Year of manufacture-1995 | Jagrutivihar MCL HQ Burla | Nos              | 1     |
| 3     | MCL/HQ/03(19-20) | SBP/MCL/HQ/Admn/18-19/03<br>Dt.24.04.19 | Scrap details arising out of the vehicles no.OR-15C-2834 Veh.Type - Deregistered Ambassador Car, Engine no.3ELJW050133, Chassis no.AAX778217, Year of manufacture-1998 | Jagrutivihar MCL HQ Burla | Nos              | 1     |
| 4     | MCL/HQ/04(19-20) | SBP/MCL/HQ/Admn/18-19/04<br>Dt.24.04.19 | Scrap details arising out of the vehicles no.OR-15C-2835 Veh.Type - Deregistered Ambassador Car, Engine no.3ELFW048706, Chassis no.AAX778226, Year of manufacture-1998 | Jagrutivihar MCL HQ Burla | Nos              | 1     |
| 5     | MCL/HQ/05(19-20) | SBP/MCL/HQ/Admn/18-19/05<br>Dt.24.04.19 | Scrap details arising out of the vehicles no.OR-15A-2556 Veh.Type - Deregistered Maruti Van, Engine no.741564, Chassis no.907365, Year of manufacture-1992             | Jagrutivihar MCL HQ Burla | Nos              | 1     |
| 6     | MCL/HQ/07(19-20) | SBP/MCL/HQ/Admn/18-19/07<br>Dt.24.04.19 | Scrap details arising out of the vehicles no.OR-15A-4762 Veh.Type - Deregistered Maruti Van, Engine no.F8BIN831259, Chassis no.ST91IN933980, Year of manufacture-1993  | Jagrutivihar MCL HQ Burla | Nos              | 1     |

|    |                      |   |   |                                    |     |   |
|----|----------------------|---|---|------------------------------------|-----|---|
| 7  | MCL/HQ/<br>08(19-20) | SBP/MCL/<br>HQ/<br>Admn/18-<br>19/08<br>Dt.24.04.19 | Scrap details arising out of the vehicles no.OR-15A-4763<br>Veh.Type - Deregistered Maruti Van, Engine no.F8BIN831539, Chassis no.ST91IN933964. Year of Regn - 1993         | Jagrutivihar<br>MCL HQ<br>Burla    | Nos | 1 |
| 8  | MCL/HQ/<br>09(19-20) | SBP/MCL/<br>HQ/<br>Admn/18-<br>19/09<br>Dt.24.04.19 | Scrap details arising out of the vehicles no.OR-15A-4764<br>Veh.Type - Deregistered Maruti Van, Engine no.F8BIN831506, Chassis no.ST91IN933978. Year of manufacturer:1993   | Jagrutivihar<br>MCL HQ<br>Burla    | Nos | 1 |
| 9  | MCL/HQ/<br>11(19-20) | SBP/MCL/<br>HQ/<br>Admn/18-<br>19/11<br>Dt.24.04.19 | Scrap details arising out of the vehicles no.OR-15B-4303 Veh Type - Deregistered Mahindra Jeep, Engine no.DU23610, Chassis no.MM540DP4CUDU 23610. Year of manufacturer:1996 | Jagrutivihar<br>MCL HQ<br>Burla    | Nos | 1 |
| 10 | HIN-01<br>(19-20)    | DO/RS-<br>HA/2019-<br>20/02<br>Dt.30.04.19          | Scrap Old & unserviceable, Deregistered Maruti Gypsy, Regd no.OR-06A-3388, Engine No.215065, Chassis no.164136.   | Regional<br>Store,<br>Hingula Area | Nos | 1 |
| 11 | HIN-02<br>(19-20)    | DO/RS-<br>HA/2019-<br>20/03<br>Dt.30.04.19          | Scrap Old & unserviceable, Deregistered Maruti Udyog Gypsy, Regd no.OR-06-8866, Engine No.183611, Chassis no.153071   | Regional<br>Store,<br>Hingula Area | Nos | 1 |
| 12 | HIN-03<br>(19-20)    | DO/RS-<br>HA/2019-<br>20/04<br>Dt.30.04.19          | Scrap Old & unserviceable, Deregistered JEEP, Regd no.OR-06A-4275, Engine No.CVR7500PH14JDT14827 Chassis no.DT14827   | Regional<br>Store,<br>Hingula Area | Nos | 1 |
| 13 | HIN-04<br>(19-20)    | DO/RS-<br>HA/2019-<br>20/05<br>Dt.30.04.19          | Scrap Old & unserviceable, Deregistered JEEP, Make-Armada , Regd no.OR-06B-6143, Engine No.188934BWDN Chassis no.DW18893  | Regional<br>Store,<br>Hingula Area | Nos | 1 |
| 14 | HIN-05<br>(19-20)    | DO/RS-<br>HA/2019-<br>20/06<br>Dt.30.04.19          | Scrap Old & unserviceable, Deregistered Ambassador Car, Regd No.OR-06-6417, Engine No.111666068, Chassis No.6eh098276   | Regional<br>Store,<br>Hingula Area | Nos | 1 |

|    |                   |   |   |   |     |   |
|----|-------------------|---|---|---|-----|---|
| 15 | HIN-06<br>(19-20) | DO/RS-<br>HA/2019-<br>20/07<br>Dt.30.04.19                          | Scrap Old & unserviceable,<br>Deregistered Maruti Udyog<br>Gypsy, Regd no.OR-06-2939,<br>Engine No.214833, Chassis<br>no.164346                             | Regional<br>Store,<br>Hingula Area          | Nos | 1 |
| 16 | LKP-11<br>(19-20) | MCL/LKPA<br>/BOCM/BU<br>S/18-19/16<br>Dt.08.10.18                   | Scrap arising out of Deregistered<br>Swaraj Mazda Cash Van Regd<br>no.OR23-4198, Engine<br>No.SLCI-066519, Chassis<br>No.NIWEL-4GM0073678                   | E&M Work<br>shop BOCM,<br>Lakhanpur<br>Area | Nos | 1 |
| 17 | LKP-13<br>(19-20) | MCL/LKPA<br>/BOCM/BU<br>S/18-19/18<br>Dt.08.10.18                   | Scrap arising out of Deregistered<br>Fire Tender on TATA LPT 1210<br>make, Regd no.OR-15A-9210,,<br>Engine No.692D22FVQ113924<br>Chassis No.344352FVQ111005 | E&M Work<br>shop BOCM,<br>Lakhanpur<br>Area | Nos | 1 |
| 18 | IBV-01<br>(19-20) | MCL/IBV/<br>RSS/DO/Su<br>rvey Off/15-<br>16/19-20/12<br>Dt.11.06.19 | Scrap arising out of Deregistered<br>Armada JEEP, Make M&M<br>D.O.REG 28.12.1994, Regd<br>No.OR-15A-8946. Year of Regn<br>- 1994                            | Regional<br>store Ib-<br>Valley Area        | Nos | 1 |
| 19 | IBV-02<br>(19-20) | MCL/IBV/<br>RSS/DO/Su<br>rvey Off/15-<br>16/19-20/13<br>Dt.11.06.19 | Scrap arising out of Deregistered<br>Armada JEEP, Make M&M<br>Model1998, Regd No.OR-15C-<br>3624  | Regional<br>store Ib-<br>Valley Area        | Nos | 1 |
| 20 | IBV-03<br>(19-20) | MCL/IBV/<br>RSS/DO/Su<br>rvey Off/15-<br>16/19-20/14<br>Dt.11.06.19 | Scrap arising out of Deregistered<br>JEEP, Make M&M D.O. REG-<br>29.11.1997, Regd No.OR-15C-<br>1179.   | Regional<br>store Ib-<br>Valley Area        | Nos | 1 |
| 21 | IBV-04<br>(19-20) | MCL/IBV/<br>RSS/DO/Su<br>rvey Off/15-<br>16/19-20/15<br>Dt.11.06.19 | Scrap arising out of Deregistered<br>JEEP, Make M&M D.O. REG-<br>16.12.1998, Regd No.OR-15C-<br>6737  | Regional<br>store Ib-<br>Valley Area        | Nos | 1 |

|    |                   |  |   |   |    |     |
|----|-------------------|--|---|---|----|-----|
| 22 | LIN-14<br>(18-19) | RS/LA/Scrap/SOR/18-19/190<br>Dt.19.11.18           | Scrap arising out of Old & Used Un-serviceable, Surveyed off De-Registered & Grounding off Hindustan Motor make FEL-2071 Front End Loader, OEM SL no.255, CIL No.FEL-167 along with engine & Transmission Regd no.OR19D6448, Engine no.6TG02570 | Lingaraj OCP<br>HEMM<br>Workshop,<br>Lingaraj Area                | MT | 20  |
| 23 | LIN-16<br>(18-19) | RS/LA/Scrap/SOR/18-19/192<br>Dt.19.11.18           | Scrap arising out of Old & Used Un-serviceable Iron & Steel Materials consisting of Cabin=30Nos, P/L=Buckets 02 Nos W/T Body 01 No, Wheel Drums, etc. of different HEMM Equipment.  | Lingaraj<br>OCP, HEMM<br>Workshop,<br>Lingaraj Area               | MT | 35  |
| 24 | TAL-07<br>(18-19) | RS(T)/TA/Survey<br>Off/2018-19/05<br>Dt.27.11.18   | Scrap Iron & Steel Material   | Regional<br>Store, Talcher<br>Area                                | MT | 50  |
| 25 | BRP-22<br>(18-19) | MCL/GM(B<br>A)/<br>RS/18-19/SOR/860<br>Dt.23.01.19 | Old Used un-serviceable scrap<br>HEMM Spares  | Jamubahali<br>Workshop,<br>Bharatpur<br>OCP,<br>Bharatpur<br>Area | MT | 15  |
| 26 | BRP-26<br>(18-19) | MCL/GM(B<br>A)/<br>RS/SOR/18-19/966<br>Dt.27.02.19 | Scrap Used un-serviceable<br>Surveyed off and De-registered<br>Dumper, Model-CAT-773D(50T), OEM SI no.BGL00227, CIL No.D-9653 with Engine only.   | Jamubahali<br>Workshop,<br>Bharatpur<br>OCP,<br>Bharatpur<br>Area | MT | 16  |
| 27 | BRP-27<br>(18-19) | MCL/GM(B<br>A)/<br>RS/SOR/18-19/967<br>Dt.27.02.19 | Scrap Used un-serviceable<br>Surveyed off Rope Shovel,<br>Model:EKG-5A, OEM<br>Sl.no.HMB-457, CIL No.EXC-2331 without M-G Set and all other Motors  | Bharatpur<br>OCP,<br>Bharatpur<br>Area                            | MT | 100 |

|    |   |  |  |  |    |    |
|----|---|--|--|--|----|----|
| 28 | BRP-28<br>(18-19)                         | MCL/GM(B<br>A)/<br>RS/SOR/18-<br>19/968<br>Dt.27.02.19     | Scrap Used un-serviceable<br>Surveyed off Dozer,<br>Model:BD355, OEM SI<br>no.G11153, CIL no.T-2688 with<br>Engine, Transmission and other<br>sub-assemblies   | Jamubahali<br>Workshop,<br>Bharatpur<br>OCP,<br>Bharatpur<br>Area  | MT | 15 |
| 29 | BRP-29<br>(18-19)                         | MCL/GM(B<br>A)/<br>RS/SOR/18-<br>19/1014<br>Dt.06.03.19    | Scrap Used un-serviceable<br>surveyed off Dozer, Make-<br>BEML, Model: BD155, OEM<br>Sl.no.G12309, CIL No.T-2602<br>with Engine only.  | Jambubahali<br>workshop,<br>Bharatpur<br>OCP,<br>Bharatpur<br>Area | MT | 15 |
| 30 | LIN-07<br>(18-19)                         | RS/LA/Scra<br>p/<br>SOR/18-<br>19/183<br>Dt.19.06.20<br>18 | Scrap arising out of Old & Used<br>Un-serviceable, Surveyed off &<br>Grounded BD-355 Dozer, OEM<br>SL No.G11154, CIL No.T-2705,<br>along with Transmission SL<br>no.H&P650L02, Engine Model<br>BS6D170& SL no.9511300962 | Lingaraj<br>OCP, HEMM<br>Workshop,<br>Lingaraj Area                | MT | 25 |
| 31 | CWS(T)-<br>03(18-19)<br>Review<br>(14-15) | GM//CWS(<br>X)/<br>TAL/SO/20<br>14-15/03<br>Dt.24.11.14    | Scrap Old Used Unserviceable<br>Iron & Steel Chips   | Iron & Steel<br>Yard Central<br>Workshop<br>(Excv),<br>Talcher     | MT | 2  |
| 32 | BRP-01<br>19-20                           | MCL/GM(B<br>A)/<br>RS/SOR/<br>19-20/35<br>Dt.12.04.19      | Scrap Old used un-serviceable,<br>Surveyed off and De-registered<br>Dumper, Model:CAT-773D 50T,<br>OEM SI No.BGL00221, CIL<br>No.D-9449 with Engine and<br>other sub-assemblies and without<br>Transmission              | Jambubahali<br>Workshop<br>Bharatpur<br>OCP<br>Bharatpur<br>Area   | MT | 16 |
| 33 | BRP-02<br>19-20                           | MCL/GM(B<br>A)/<br>RS/SOR/<br>19-20/36<br>Dt.12.04.19      | Scrap Old used un-serviceable,<br>Surveyed off and De-registered<br>Dumper, Model:CAT-773D 50T,<br>OEM SI No.BGL00220, CIL<br>No.D-9448 with Engine and<br>other sub-assemblies and without<br>Transmission              | Jambubahali<br>Workshop<br>Bharatpur<br>OCP<br>Bharatpur<br>Area   | MT | 16 |
| 34 | BRP-03<br>19-20                           | MCL/GM(B<br>A)/<br>RS/SOR/<br>19-20/37<br>Dt.12.04.19      | Scrap Old used un-serviceable,<br>Surveyed off and De-registered<br>Dumper, Model:CAT-773D 50T,<br>OEM SI No.BGL00231, CIL<br>No.D-9655 with Engine and<br>other sub-assemblies and without<br>Transmission              | Jambubahali<br>Workshop<br>Bharatpur<br>OCP<br>Bharatpur<br>Area   | MT | 16 |

|    |                 |   |   |  |     |     |
|----|-----------------|---|---|--|-----|-----|
| 35 | BRP-04<br>19-20 | MCL/GM(B<br>A)/<br>RS/SOR/<br>19-20/38<br>Dt.12.04.19               | Scrap Old used un-serviceable,<br>Surveyed off and De-registered<br>Dumper, Model:CAT-773D 50T,<br>OEM SI No.BGL00218, CIL<br>No.D-9446 with Engine and<br>other sub-assemblies and without<br>Transmission | Jambubahali<br>Workshop<br>Bharatpur<br>OCP<br>Bharatpur<br>Area | MT  | 16  |
| 36 | BRP-06<br>19-20 | MCL/GM(B<br>A)/<br>RS/19-<br>20/SR/258<br>Dt.29.06.19               | Scrap old used unserviceable<br>Drill Bit Size i. 6 1/4 - 139 Nos<br>ii.9 7/8 - 14 Nos iii. 10 5/8 - 04<br>Nos Lot 157 Nos  | Regional<br>Store<br>Bharatpur<br>Area                           | Lot | 1   |
| 37 | BRP-07<br>19-20 | MCL/GM(B<br>A)/<br>RS/19-<br>20/SR/259<br>Dt.29.06.19               | Scrap old used unserviceable<br>mixed Iron and Steel scrap of<br>RLS Systems  | Bharatpur<br>OCP<br>Bharatpur<br>Area                            | MT  | 15  |
| 38 | BRP-08<br>19-20 | MCL/GM(B<br>A)/RS/19-<br>20/SR/260<br>Dt.29.06.19                   | Scrap and old used unserviceable<br>Mixed Iron and Steel of Feeder<br>Breaker/CHP system like<br>Crusher roll, Receiving Hopper,<br>Conveyor Chain, Rollers,<br>Brackets, EMV Feeder etc.                   | Bharatpur<br>OCP<br>Bharatpur<br>Area                            | MT  | 30  |
| 39 | TAL-01<br>19-20 | 4652/Surve<br>y Off/18-<br>19/02<br>Dt.16.03.19                     | Scrap Old and Used<br>unserviceable Iron and Steel  | Colliery<br>Store, Talcher<br>Colliery,<br>Talcher Area          | MT  | 30  |
| 40 | LKP-10<br>19-20 | MCL/LKPA<br>/ LKP<br>OCP/US/18<br>-19/151<br>Dt.25.02.19            | Scrap Mixed Iron and Steel<br>arising out of HEMM   | HEMM Scrap<br>Yard LKP<br>OCP,<br>Lakhanpur<br>Area              | MT  | 100 |
| 41 | LKP-18<br>19-20 | MCL/LKPA<br>/<br>Lilari/PO/E<br>xcv/ US/18-<br>19/04<br>Dt.28.11.18 | Scrap arising out of TATA<br>HITACHI hydraulic Excavator<br>EX-300 SL no.481, CIL<br>No.EXC-2242 without Engine<br>and Electrical Assemblies  | Excavation<br>Workshop<br>Lilari OCP,<br>Lakhanpur<br>Area       | MT  | 20  |