

LIST OF SCRAP LOTS FOR E-AUCTION NO. ASL/MCL/DISPOSAL/21-22/08
DATED 20/07/2021

Lot no	MCL Control No.	Area Lot No.	Survey off Report no	Material Descp	Location	UOM	QTY
1	IBV-06 (20-21)	41	MCL/IBV/RSS/ DO/SURVEY OFF/20-21/41 DT.14-09-2020	Iron & Steel Scrap Arising out of Grounded BD355 Dozer, OEM NO SL NO.11301/CIL NO.T- 2856, DOC – 02.09.2008 With Engine & Transmission	Samaleswari OCP, IB Valley Area	MT	30
2	IBV-10 (20-21)	45	MCL/IBV/RSS/ DO/SURVEY OFF/20-21/45 DT.14-09-2020	Iron & Steel Scrap Arising out of Grounded BEML 210M 50T, OEM NO SL NO. 2886/CIL NO. D-9263, DOC-05.01.2006 Without Engine & Transmission	Samaleswari OCP, IB Valley Area	MT	30
3	IBV-11 (20-21)	46	MCL/IBV/RSS/ DO/SURVEY OFF/20-21/46 DT.14-09-2020	Iron & Steel Scrap Arising out of Grounded BEML 210M 50T Dumper, OEM NO SL NO.2885/CIL NO.D-9168, DOC- 08.12.2005 Without Engine & Transmission	Samaleswari OCP, IB Valley Area	MT	30
4	IBV-12 (20-21)	47	MCL/IBV/RSS/ DO/SURVEY OFF/20-21/47 DT.14-09-2020	Iron & Steel Scrap Arising out of Grounded Promtractor Dozer, OEM NO SL NO.000224/CIL NO.T-3069, DOC-14.12.2010 Without Engine & Transmission	Samaleswari OCP, IB Valley Area	MT	30
5	IBV-24 (20-21)	63	MCL/SBP/EXC V/2020/HEM- 8/2118 DT.06.11.2020	Iron & Steel Scrap Arising out of Grounded DOZER,CIL NO.T- 3077 OEM NO -237, D.O.C- 29.06.2011 Without Engine & Transmission	At workshop Area, Lajkura OCP, IB Valley Area	MT	30
6	IBV-25 (20-21)	62	MCL/SBP/EXC V/2019/HEM- 8/927 DT.18.06.2020	Iron & Steel Scrap Arising out of Grounded Dill, CIL NO.RD-487, OEM NO 6010003, D.O.C- 17.08.2001 Without Major Sub Assy	At workshop Area, Lajkura OCP, IB Valley Area	MT	30
7	IBV-26 (20-21)	60	MCL/SBP/EXC V/2020/HEM- 8/964 DT.25.06.2020	Iron & Steel Scrap Arising out of Grounded DOZER,CIL NO.T- 3037 OEM NO -230 D.O.C- 05.12.2010 Without Engine & Transmission	At workshop Area, Lajkura OCP, IB Valley Area	MT	30
8	IBV-27 (20-21)	59	MCL/SBP/EXC V/2019/HEM- 8/08 DT.02.01.2019	Iron & Steel Scrap Arising out of Grounded DOZER,CIL NO.T- 2865 OEM NO -11354, D.O.C- 20.03.2009 Without Engine & Transmission	At workshop Area, Lajkura OCP, IB Valley Area	MT	25
9	IBV-28 (20-21)	58	MCL/SBP/EXC V/2015/HEM- 8/2237 DT.23.11.2015	Iron & Steel Scrap Arising out of Grounded Dozer, CIL NO.T- 2713, OEM NO -11102, D.O.C- 03.05.2005 Without Engine & Transmission	At workshop Area, Lajkura OCP, IB Valley Area	MT	27
10	IBV-29 (20-21)	64	MCL/SBP/EXC V/2020/HEM- 8/305 DT.25.02.2020	Iron & Steel Scrap Arising out of Grounded Excavator H55N Demag, CIL NO.Exc-2579, OEM NO - 55007 D.O.C-10.04.2009 Without Engine & Transmission	At workshop Area, Lajkura OCP, IB Valley Area	MT	20

LIST OF SCRAP LOTS FOR E-AUCTION NO. ASL/MCL/DISPOSAL/21-22/08
DATED 20/07/2021

11	IBV-30 (20-21)	61	MCL/SBP/EXC V/2020/HEM- 8/305 DT.25.02.2020	Iron & Steel Scrap Arising out of Grounded Excavator H55N Demag, CIL NO.Exc-2573, OEM NO -55008 D.O.C-20.04.2009 Without Engine & Transmission	At workshop Area, Lajkura OCP, IB Valley Area	MT	20
12	IBV-31 (20-21)	68	MCL/IBV/RSS/ DO/Survey off/2021/04 dt.27/02/21	Iron and steel scrap arising out of grounded BEML BH-50M-1 60T Dumper, OEM SL no.3318/CIL No.D-10676, DOC-15/03/2010 without Engine and transmission	Samaleswari OCP, IB- Valley Area	MT	30
13	IBV-32 (20-21)	69	MCL/IBV/RSS/ DO/Survey off/2021/05 dt.27/02/21	Iron and steel scrap arising out of grounded Atlas coppco make 160MM Model-IDM-30 Drill, OEM SL no.200605653/CIL No.RDC-1045 without Engine and useful spares	Samaleswari OCP, IB- Valley Area	MT	20
14	IBV-33 (20-21)	70	MCL/IBV/RSS/ DO/Survey off/2021/06 dt.27/02/21	Iron and steel scrap arising out of grounded BH-50M 50T Dumper, OEM SL no.3161/CIL No.10284, DOC-17/03/2009 without Engine and transmission	Samaleswari OCP, IB- Valley Area	MT	30
15	IBV-34 (20-21)	71	MCL/IBV/RSS/ DO/Survey off/2021/07 dt.27/02/21	Iron and steel scrap arising out of grounded BEML BEML 28KL Water Tanker OEM SL no.325/CIL No.WS-192, DOC- 30/07/2009 with Engine and transmission	Samaleswari OCP, IB- Valley Area	MT	30
16	IBV-35 (20-21)	72	MCL/IBV/RSS/ DO/Survey off/2021/08 dt.27/02/21	Iron and steel scrap arising out of grounded BEML BH-50M-1 60T Dumper, OEM SL no.3323/CIL No.D-10678, DOC-04/03/2010 without Engine and transmission	Samaleswari OCP, IB- Valley Area	MT	30
17	IBV-36 (20-21)	73	MCL/IBV/RSS/ DO/Survey off/2021/09 dt.27/02/21	Iron and steel scrap arising out of grounded BEML 210M 50T Dumper, OEM SL no.2889/CIL No.D-9161, DOC-30/12/2005 without Engine and transmission	Samaleswari OCP, IB- Valley Area	MT	30
18	IBV-37 (20-21)	74	MCL/IBV/RSS/ DO/Survey off/2021/10 dt.27/02/21	Iron and steel scrap arising out of grounded BEML 50 -M-1 60T Dumper, OEM SL no.3380/CIL No.D-10884, DOC-15/11/2010 without Engine and transmission	Samaleswari OCP, IB- Valley Area	MT	30
19	IBV-38 (20-21)	75	MCL/IBV/RSS/ DO/Survey off/2021/11 dt.27/02/21	Iron and steel scrap arising out of grounded BEML 50 -M-1 60T Dumper, OEM SL no.3333/CIL No.D-10820, DOC-13/05/2020 without Engine and transmission	Samaleswari OCP, IB- Valley Area	MT	30
20	IBV-39 (20-21)	76	MCL/IBV/RSS/ DO/Survey off/2021/12 dt.27/02/21	Iron and steel scrap arising out of grounded BEML 210M 50T Dumper, OEM SL no.2923/CIL No.D-9433, DOC-26/05/2006 without Engine and transmission	Samaleswari OCP, IB- Valley Area	MT	30
21	IBV-40 (20-21)	77	MCL/IBV/RSS/ DO/Survey off/2021/13 dt.27/02/21	Iron and steel scrap arising out of grounded BH 50 M 50T Dumper, OEM SL no.3164/CIL No.D- 10285, DOC-03/03/2009 without Engine and transmission	Samaleswari OCP, IB- Valley Area	MT	30