

LIST OF SCRAP LOTS FOR E-AUCTION NO. ASL/MCL/DISPOSAL/21-22/12
DATED 22/09/2021

Lot no	MCL Control No.	Area Lot No.	Survey off Report no	Material Descp	Location	UOM	QTY
1	JGN-03 (21-22)	92	4741/RS(JA)S. Off/19-20/92 dt.04/03/2020	Old & used scrap arising of survey off of BD355 Dozer, SI no.G11107, CIL No.T2529, DOC-01/05/2005, without engine & transmission	Excavation workshop, Bhubaneswari OCP, Jagannath Area	MT	16
2	JGN-04 (21-22)	2	4741/RS(JA)S. Off/21-22/02 dt.08/06/2021	Old & used scrap arising of survey off Water Sprinkler 28KL, WS-282, OEM No.0363, CIL No.WS-220, DOC-18/07/2010, without engine & transmission	Excavation workshop, Bhubaneswari OCP, Jagannath Area	MT	17
3	HIN-15 (21-22)	15	PO (BOCP) Store/2020- 21/095 dt.08.09.2020	Scrap unserviceable, surveyed off & de-registered Explosive Van, OR 06-4452, CH NO.- RVE275565, Mfd. yr.-07/1992	Balaram OCP, Hingula Area	No	1
4	HIN-19 (21-22)	19	DO/RS-HA/21- 22/19 Date- 09/08/2021	Old & used un-serviceable Iron Scrap	Unit Store, Balram OCP, Hingula Area	MT	30
5	HIN-25 (21-22)	25	DO/RS-HA/21- 22/25 Date- 09/08/2021	Scrap arising out of Equip - Dumper, Make - BEML, Model - BH50M, OEM No. - 2939, CIL No. - D9638, D.O.C. - 19/05/2006, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	28
6	HIN-26 (21-22)	26	DO/RS-HA/21- 22/26 Date- 09/08/2021	Scrap arising out of Equip - Dumper, Make - BEML, Model - 210M, OEM No. - 2595, CIL No. - D7811, D.O.C. - 30/07/1999, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	28
7	HIN-28 (21-22)	28	DO/RS-HA/21- 22/28 Date- 09/08/2021	Scrap arising out of Equip - Dumper, Make - BEML, Model - BH50M-1, OEM No. - 3348, CIL No. - D10914, D.O.C. - 09/09/2010, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	28
8	HIN-29 (21-22)	29	DO/RS-HA/21- 22/29 Date- 09/08/2021	Old & Used Un-Serviceble Scrap Iron	Dumper workshop, Balram OCP, Hingula Area	MT	120

9	HIN-30 (21-22)	30	DO/RS-HA/21-22/30 Date-09/08/2021	Scrap arising out of Equip - Water Sprinkler, Make - BEML, Model - WS - 28, OEM No.- 279, CIL No.- WS - 168, D.O.C. - 02/04/2008, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	18
10	HIN-31 (21-22)	31	DO/RS-HA/21-22/31 Date-09/08/2021	Scrap arising out of Equip - Dumper, Make - BEML, Model - BH50M, OEM No. - 2950, CIL No. - D9635, D.O.C. - 19/06/2006, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	28
11	HIN-32 (21-22)	32	DO/RS-HA/21-22/32 Date-09/08/2021	Scrap arising out of Equip - Dumper, Make - BEML, Model - BH50M, OEM No. - 2945, CIL No. - D9636, D.O.C. - 10/06/2006, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	28
12	HIN-33 (21-22)	33	DO/RS-HA/21-22/33 Date-09/08/2021	Scrap arising out of Equip - Dumper, Make - BEML, Model - 210M, OEM No.- 2647, CIL No.- D8098, D.O.C. -26/02/2000, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	28
13	HIN-34 (21-22)	34	DO/RS-HA/21-22/34 Date-09/08/2021	Scrap arising out of Equip - Dumper, Make - BEML, Model - 210M, OEM No.- 2594, CIL No.- D7814, D.O.C. -12/08/1999, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	28
14	HIN-36 (21-22)	36	DO/RS-HA/21-22/36 Date-09/08/2021	Scrap arising out of Equip - Dumper, Make - BEML, Model - BH50M, OEM No. - 3154, CIL No. - D10270, D.O.C. -06/01/2009, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	28
15	HIN-37 (21-22)	37	DO/RS-HA/21-22/37 Date-09/08/2021	Scrap arising out of Equip - Dumper, Make - BEML, Model - BH50M, OEM No.- 3159, CIL No.- D10271, D.O.C. -11/01/2009, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	28

16	HIN-38 (21-22)	38	DO/RS-HA/21-22/38 Date-09/08/2021	Scrap arising out of Equip - Dumper, Make - BEML, Model - BH50M-1, OEM No.- 3342, CIL No. - D10911, D.O.C. - 20/07/2010, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	28
17	HIN-39 (21-22)	39	DO/RS-HA/21-22/39 Date-09/08/2021	Scrap arising out of Equip - Dumper, Make - BEML, Model - BH50M-1, OEM No.- 3340, CIL No.- D10910, D.O.C. - 22/07/2010, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	28
18	HIN-41 (21-22)	41	DO/RS-HA/21-22/41 Date-09/08/2021	Scrap arising out of Equip - Dumper, Make - BEML, Model - BH50M-1, OEM No.- 3347, CIL No.- D10913, D.O.C. - 20/07/2010, without Engine, Transmission, Radiator & serviceable parts	HEMM Workshop, Hingula OCP, Hingula Area	MT	28
19	TAL-03 (21-22)	4	4650/Survey off/2021-22/02 Dt.04/06/2021	Scrap surveyed off Side Dump Loader in dismantled condition, Make: EIMCO ELECON, Model:625, SL.NO.1446, DOC:18.12.10, excluding electric motor	Talcher Colliery, Talcher Area	MT	6.5
20	TAL-04 (21-22)	5	4650/Survey off/2021-22/03 Dt.04/06/2021	Scrap surveyed Off used & unserviceable M.S. Structure of Coal Handling Plant (CHP) comprising of ISMB, ISA, ISMC, M.S. Plate, etc of various sizes	Talcher Colliery, Talcher Area	MT	78
21	TAL-05 (21-22)	3	4650/Survey off/2021-22/01 Dt.04/06/2021	Scrap surveyed off Side Dump Loader in dismantled condition Make: EIMCO ELECON, Model:625, SL.NO.1441, DOC:26.11.10, excluding electric motor	Talcher Colliery, Talcher Area	MT	6.5
22	MCL HQ-01 (21-22)	1	SBP/MCL/HQ/ Admn/21-22/ 1073 dt.23/08/21	Scrap details arising out of the surveyed off & de-registered vehicles no. Regd no.OR-15M-1579, Veh Type- AMBASSADOR CAR, Engine no.3ELAH106664, Chassis no.ACH918880, Mfg. year-2008.	Jagruti Vihar, MCL HQ, Burla	No	1

23	MCL HQ-02 (21-22)	2	SBP/MCL/HQ/ Admn/21-22/ 1074 dt.23/08/21	Scrap details arising out of the surveyed off & de-registered vehicles no. Regd no.OR-15M-1581, Veh Type- AMBASSADOR CAR, Engine no.3ELBH106953, Chassis no.ACH9121, Mfg. year - 2008.	Jagruti Vihar, MCL HQ, Burla	No	1
24	MCL HQ-03 (21-22)	3	SBP/MCL/HQ/ Admn/21-22/ 1075 dt.23/08/21	Scrap details arising out of the surveyed off & de-registered vehicles no. Regd no.OR-15M-6037, Veh Type- AMBASSADOR CAR, Engine no.3ELBHH108260, Chassis no.AJH922956, Mfg. year- 2008.	Jagruti Vihar, MCL HQ, Burla	No	1
25	MCL HQ-04 (21-22)	4	SBP/MCL/HQ/ Admn/21-22/ 1076 dt.23/08/21	Scrap details arising out of the surveyed off & de-registered vehicles no. Regd no.OR-15C-8403, Veh Type- Mahindra Jeep, Engine no.PW04114, Chassis no.M4540DP4KWDW04114 , Mfg. year -1998.	Anand Vihar, MCL HQ, Burla	No	1
26	MCL HQ-05 (21-22)	5	SBP/MCL/HQ/ Admn/21-22/ 1077 dt.23/08/21	Scrap details arising out of the surveyed off & de-registered vehicles no. Regd no.OR-15C-2834, Veh Type- AMBASSADOR CAR, Engine no.3ELJW050133, Chassis no.AAX778217, Mfg. year- 1998.	Jagruti Vihar, MCL HQ, Burla	No	1
27	MCL HQ-06 (21-22)	6	SBP/MCL/HQ/ Admn/21-22/ 1078 dt.23/08/21	Scrap details arising out of the surveyed off & de-registered vehicles no. Regd no.OR-15C-2835, Veh Type- AMBASSADOR CAR, Engine no.3ELFW048706, Chassis no.AAX778226, Mfg. year- 1998.	Jagruti Vihar, MCL HQ, Burla	No	1