

**LIST OF SCRAP LOTS FOR E-AUCTION NO. ASL/MCL/DISPOSAL/21-22/04**  
**DATED 08/07/2021**

| Sl No | MCL Control no.   | Area Lot No | Survey off Report no & Dt                 | Material description                                                                                                                                                           | Location                           | UOM | QTY |
|-------|-------------------|-------------|-------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------|-----|-----|
| 1     | MCL HQ-01 (20-21) | 1           | SBP/MCL/HQ /Admn/20-21/1326 dt.27/06/2020 | Scrap details arising out of the de-registered Vehicle no.OR-15D-0526, School Bus.32S, Engine no. 497D22HRS753664 Chassis no.386026HRS707017. Year of manufacturer 1998        | Anand Vihar, MCL HQ, Burla         | No  | 1   |
| 2     | MCL HQ-02 (20-21) | 2           | SBP/MCL/HQ /Admn/20-21/1327 dt.27/06/2020 | Scrap details arising out of the de-registered Vehicle no.OR-15D-7242, Gypsy Engine no. F10A-IN-248200 Chassis no. SJ41-IN-197475. Year of manufacture-1999                    | Jagruti Vihar, MCL HQ, Burla       | No  | 1   |
| 3     | MCL HQ-03 (20-21) | 3           | SBP/MCL/HQ /Admn/20-21/1328 dt.27/06/2020 | Scrap details arising out of the de-registered Vehicle no.OR-15B-1984, Mini Truck, Engine no.497SP21CVQ719514 Chassis no. 357010CVQ808067. Year of manufacturer 1994           | Jagruti Vihar, MCL HQ, Burla       | No  | 1   |
| 4     | MCL HQ-04 (20-21) | 4           | SBP/MCL/HQ /Admn/20-21/1329 dt.27/06/2020 | Scrap details arising out of the de-registered Vehicle no.OR-15M-1577, Ambassador Car Engine no.3ELBH106951, Chassis no.ACH919122 year of manufacturer:2008                    | Jagruti Vihar, MCL HQ, Burla       | No  | 1   |
| 5     | MCL HQ-06 (20-21) | 1           | SBP/MCL/HQ /Admin/20-21/313 Dt.01.01.2021 | Scrap details arising out of the de-registered Vehicle No.OR-15B-9671, Veh. type SCHOOL BUS, Engine No. 697D28GTQ134893, Chassis no. 359350GTQ010252, year of manufacture:1996 | Anand Vihar, MCL HQ, Burla         | No  | 1   |
| 6     | MCL HQ-07 (20-21) | 2           | SBP/MCL/HQ /Admin/20-21/313 Dt.01.01.2021 | Scrap details arising out of the de-registered Vehicle No.OR-02BB-6505, Veh. type AMBASSADOR, Engine No. 3ELKJ110587, Chassis no. MA7AM18MLJU004564, year of manufacture:2009  | Jagruti Vihar, MCL HQ, Burla       | No  | 1   |
| 7     | MCL HQ-08 (20-21) | 3           | SBP/MCL/HQ /Admin/20-21/314 Dt.01.01.2021 | Scrap details arising out of the de-registered Vehicle No.WB-02F-6235, Veh. type AMBASSADOR, Engine No.3ELAW045416, Chassis no.ADW791794, year of manufacture:1997             | Jagruti Vihar, MCL HQ, Burla       | No  | 1   |
| 8     | LKP-13 (19-20)    | 18          | MCL/LKPA/B OCM/BUS/18-19/18 Dt.08.10.18   | Scrap arising out of de-registered Fire Tender on TATA LPT 1210 make, Regd no.OR-15A-9210, Engine No.692D22FVQ113924 Chassis No.344352FVQ111005                                | E&M Work shop BOCM, Lakhanpur Area | No  | 1   |

|    |                            |    |                                                                  |                                                                                                                                                                           |                                                            |     |     |
|----|----------------------------|----|------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|-----|-----|
| 9  | IBV-09<br>(19-20)          | 21 | MCL/IBV/RS<br>S/DO/Survey<br>Off/19-20/21<br>Dt.06/08/19         | Scrap Old used &<br>Unserviceable Old Drill Bits 6<br>1/4"                                                                                                                | Regional store,<br>IB-Valley Area                          | Nos | 165 |
| 10 | IBV-10<br>(19-20)          | 23 | MCL/IBV/RS<br>S/DO/Survey<br>Off/19-20/23<br>Dt.06/08/19         | Scrap Old used &<br>Unserviceable Old Drill Bits 10<br>5/8"                                                                                                               | Regional store,<br>IB-Valley Area                          | Nos | 6   |
| 11 | IBV-16<br>(19-20)          | 22 | MCL/IBV/RS<br>S/DO/Survey<br>Off/19-20/22<br>Dt.06/08/19         | Scrap Old used &<br>Unserviceable Old Drill Bits 9<br>7/8"                                                                                                                | Regional store,<br>IB-Valley Area                          | Nos | 31  |
| 12 | HIN-16<br>(19-20)          | 19 | DO/RS-<br>HA/19-20/18<br>Dt.08.08.19                             | Scrap Old & Used<br>Unserviceable de-registered<br>Ambassador Car, Regd No.<br>OR06 A-7341, Engine No:-<br>AGV743895, Chassis<br>No.CEDGVI50597                           | Regional Store,<br>Hingula Area                            | No  | 1   |
| 13 | HIN-21<br>(19-20)          | 23 | DO/HA/19-<br>20/22<br>Dt.07.11.19                                | Scrap Old & Unserviceable de-<br>registered Maruti Udyog<br>Gypsy, Regd. no. OR 06 -4107                                                                                  | Regional Store,<br>Hingula Area                            | No  | 1   |
| 14 | LKP-28<br>(19-20)          | 11 | MCL/GM/LK<br>PA/SOR/19-<br>20/27<br>Dt.05/11/19                  | Scrap arising out of de-<br>registered Omni Van having<br>Regd.no.OR-15A-2557, Engine<br>no.741299, Chassis No.907353                                                     | Regional<br>/Central store,<br>Belpahar,<br>Lakhanpur Area | No  | 1   |
| 15 | LKP-29<br>(19-20)          | 13 | MCL/GM/LK<br>PA/SOR/19-<br>20/28<br>Dt.05/11/19                  | Scrap arising out of de-<br>registered Ambassador Car<br>having Regd.no.OR-51A-4812,<br>Engine no.III 666093 Chassis<br>No.6EH098297                                      | Regional<br>/Central store,<br>Belpahar,<br>Lakhanpur Area | No  | 1   |
| 16 | LKP-30<br>(19-20)          | 7  | MCL/GM/LK<br>PA/SOR/19-<br>20/29<br>Dt.05/11/19                  | Scrap arising out of de-<br>registered Mahendra Jeep<br>having Regd.no.OSD-5790,<br>Engine no.DN33906, Chassis<br>no.DN33906                                              | Regional<br>/Central store,<br>Belpahar,<br>Lakhanpur Area | No  | 1   |
| 17 | LKP-31<br>(19-20)          | 8  | MCL/GM/LK<br>PA/SOR/19-<br>20/30<br>Dt.05/11/19                  | Scrap arising out of de-<br>registered Mahendra Jeep<br>having Regd.no.OR-15A-5002,<br>Engine no. MM540DP4D<br>R03283, Chassis no.DR03283                                 | Regional<br>/Central store,<br>Belpahar,<br>Lakhanpur Area | No  | 1   |
| 18 | LKP-32<br>(19-20)          | 9  | MCL/GM/LK<br>PA/SOR/19-<br>20/31<br>Dt.05/11/19                  | Scrap arising out of de-<br>registered Maruti Gypsy having<br>Regd.no.ORW-0388, Engine<br>no.122515, Chassis no.125218                                                    | Regional<br>/Central store,<br>Belpahar,<br>Lakhanpur Area | No  | 1   |
| 19 | LKP-33<br>(19-20)          | 10 | MCL/GM/LK<br>PA/SOR/19-<br>20/32<br>Dt.05/11/19                  | Scrap arising out of de-<br>registered Omni Van having<br>Regd.no.OR-15A-4761, Engine<br>no.F8BIN795230, Chassis<br>No.ST911N922260                                       | Regional<br>/Central store,<br>Belpahar,<br>Lakhanpur Area | No  | 1   |
| 20 | CWS<br>(IBV)-04<br>(19-20) | -  | MCL/GM/CW<br>S/IBV/RS/Sur<br>vey Off/19-<br>20/04<br>Dt.04/12/19 | Scrap arising out of de-<br>registered Old & Used<br>Unserviceable Maruti Omni<br>Ambulance Regd.no.OR15C-<br>8853, Engine<br>no.F88IN1728959, Chassis<br>No.ST911N278162 | Workshop<br>Premises, CWS<br>IB-Valley                     | No  | 1   |