

**LIST OF SCRAP LOTS FOR E-AUCTION NO. ASL/MCL/DISPOSAL/20-21/11**  
**DATED 04/02/2021**

| Lot no | MCL Control No.   | Area Lot No. | Survey off Report no                       | Material Descp  | Location  | UOM | QTY |
|--------|-------------------|--------------|--|---|---|-----|-----|
| 1      | HIN-39 (20-21)    | 60           | DO/RS-HA/20-21/60 Dt.27/08/20              | Scrap BH-60T Dumper OEM no.3375,CIL No.-D10918 without engine and without transmission  | Dumper Workshop, Balaram OCP Hingula Area           | MT  | 25  |
| 2      | HIN-40 (20-21)    | 61           | DO/RS-HA/20-21/61 Dt.27/08/20              | Scrap BH-60T Dumper OEM no.3392,CIL No.-D10926 without engine and without transmission  | Dumper Workshop, Balaram OCP Hingula Area           | MT  | 25  |
| 3      | MCL HQ-06 (20-21) | 1            | SBP/MCL/HQ/Ad min/20-21/ 313 Dt.01.01.2021 | Scrap details arising out of the Vehicle No.OR-15B-9671 Veh .type SCHOOL BUS, Engine No.697D28GTQ134893 Chassis no.359350GTQ010252 year of manufacture:1996 | Anand Vihar, MCL HQ, Burla                          | Nos | 1   |
| 4      | MCL HQ-07 (20-21) | 2            | SBP/MCL/HQ/Ad min/20-21/ 313 Dt.01.01.2021 | Scrap details arising out of the Vehicle No.OR-02BB-6505 Veh .type AMBASSADOR, Engine No.3ELKJ110587 Chassis no.MA7AM18MLJU004564 year of manufacture:2009  | Jagruti Vihar, MCL HQ, Burla                        | Nos | 1   |
| 5      | MCL HQ-08 (20-21) | 3            | SBP/MCL/HQ/Ad min/20-21/ 313 Dt.01.01.2021 | Scrap details arising out of the Vehicle No.WB-02F-6235 Veh .type AMBASSADOR, Engine No.3ELAW045416 Chassis no.ADW791794 year of manufacture:1997           | Jagruti Vihar, MCL HQ, Burla                        | Nos | 1   |
| 6      | BRP-11 (20-21)    | 199          | MCL/GM(BA)/S OR/2020-21/16 DT.16.12.2020   | Old used un-serviceable, HEMM Dumper Scraps.  | Jambubahali Workshop, Bharatpur OCP, Bharatpur Area | MT  | 30  |
| 7      | BRP-12 (20-21)    | 200          | MCL/GM(BA)/S OR/2020-21/17 DT.16.12.2020   | Old used un-serviceable, Surveyed off, Grounded Dozer, Make:Promotractor, Model: T25-01C1B1,OEM SL NO.223,CIL No:T3402,without Engine and Transmission.     | Jambubahali Workshop, Bharatpur OCP, Bharatpur Area | MT  | 16  |
| 8      | BRP-13 (20-21)    | 201          | MCL/GM(BA)/S OR/2020-21/18 DT.16.12.2020   | Old used un-serviceable, Surveyed off, Grounded Dozer, Make:BEML, Model: BD-355,OEM SL NO.G-11352,CIL No:T-2883,without Engine and Transmission.            | Jambubahali Workshop, Bharatpur OCP, Bharatpur Area | MT  | 18  |
| 9      | BRP-14 (20-21)    | 202          | MCL/GM(BA)/S OR/2020-21/19 DT.16.12.2020   | Old used un-serviceable, Surveyed off, Grounded Dozer, Make:BEML, Model: BD-355,OEM SL NO.G-11308,CIL No:T-2882,without Engine and Transmission.            | Jambubahali Workshop, Bharatpur OCP, Bharatpur Area | MT  | 18  |
| 10     | BRP-15 (20-21)    | 203          | MCL/GM(BA)/S OR/2020-21/20 DT.16.12.2020   | Old used un-serviceable, Surveyed off, Grounded Dozer, Make:BEML, Model: D-155,OEM SL NO.G-12960,CIL No:T-2950,without Engine and Transmission.             | Jambubahali Workshop, Bharatpur OCP, Bharatpur Area | MT  | 16  |

**LIST OF SCRAP LOTS FOR E-AUCTION NO. ASL/MCL/DISPOSAL/20-21/11**  
**DATED 04/02/2021**

|    |                   |     |  |   |   |    |     |
|----|-------------------|-----|--|---|---|----|-----|
| 11 | BRP-16<br>(20-21) | 204 | MCL/GM(BA)/S<br>OR/2020-21/21<br>DT.16.12.2020             | Old used un-serviceable, Surveyed off, Grounded Dozer, Make:BEML, Model: BD-155,OEM SL NO.G-12751,CIL No:T-2884,without Engine and Transmission.                            | Jambubahali Workshop, Bharatpur OCP, Bharatpur Area | MT | 16  |
| 12 | BRP-17<br>(20-21) | 206 | MCL/GM(BA)/S<br>OR/2020-21/23<br>DT.16.12.2020             | Old used un-serviceable, Surveyed off, Grounded Rope Shovel, Make:HEC, Model: EQC-5A,OEM SL NO.HMB-458,CIL No:EXC-2332 without Motor, Compressor Engine and Transmission.   | Bharatpur Mines, Bharatpur OCP, Bharatpur Area      | MT | 100 |
| 13 | BRP-18<br>(20-21) | 207 | MCL/GM(BA)/S<br>OR/2020-21/24<br>DT.16.12.2020             | Old used un-serviceable, Surveyed off, Grounded Drill, Make:Atlas Copco, Model: IDM-70E,OEM SL NO.9010041,CIL No:RD-317, without Motor, Compressor Engine and Transmission. | Jambubahali Workshop, Bharatpur OCP, Bharatpur Area | MT | 18  |
| 14 | BRP-19<br>(20-21) | 208 | MCL/GM(BA)/S<br>OR/2020-21/25<br>DT.16.12.2020             | Old used un-serviceable, Surveyed off, Grounded Drill, Make:REL, Model: RECP-650,OEM SL NO.6020805,CIL No:RDC-1146, without Engine and Transmission.                        | Jambubahali Workshop, Bharatpur OCP, Bharatpur Area | MT | 12  |
| 15 | IBV-06<br>(20-21) | 41  | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/41<br>DT.14-09-2020 | Iron & Steel Scrap Arising out of Grounded BD355 Dozer, OEM NO SL NO.11301/CIL NO.T-2856 With Engine & Transmission   | Samaleswari OCP, IB Valley Area                     | MT | 30  |
| 16 | IBV-07<br>(20-21) | 42  | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/42<br>DT.14-09-2020 | Iron & Steel Scrap Arising out of Grounded BD355 Dozer, OEM NO SL NO.11355/CIL NO.T-3430 DOC-18.03.2009 Without Engine & Transmission                                       | Samaleswari OCP, IB Valley Area                     | MT | 30  |
| 17 | IBV-09<br>(20-21) | 44  | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/44<br>DT.14-09-2020 | Iron & Steel Scrap Arising out of Grounded BEML BH-50M 50T Dumper, OEM NO SL NO.3160/CIL NO.D-10283, DOC-03.03.2009 Without Engine & Transmission                           | Samaleswari OCP, IB Valley Area                     | MT | 30  |
| 18 | IBV-10<br>(20-21) | 45  | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/45<br>DT.14-09-2020 | Iron & Steel Scrap Arising out of Grounded BEML BH-210M 50T Dumper, OEM NO SL NO.2886/CIL NO.D-9263, DOC-05.01.2006 Without Engine & Transmission                           | Samaleswari OCP, IB Valley Area                     | MT | 30  |
| 19 | IBV-11<br>(20-21) | 46  | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/46<br>DT.14-09-2020 | Iron & Steel Scrap Arising out of Grounded BEML BH-210M 50T Dumper, OEM NO SL NO.2885/CIL NO.D-9168, DOC-08.12.2005 Without Engine & Transmission                           | Samaleswari OCP, IB Valley Area                     | MT | 30  |
| 20 | IBV-12<br>(20-21) | 47  | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/47<br>DT.14-09-2020 | Iron & Steel Scrap Arising out of Grounded Promtractor Dozer, OEM NO SL NO.000224/CIL NO.T-3069, DOC-14.12.2010 Without Engine & Transmission                               | Samaleswari OCP, IB Valley Area                     | MT | 30  |

**LIST OF SCRAP LOTS FOR E-AUCTION NO. ASL/MCL/DISPOSAL/20-21/11**  
**DATED 04/02/2021**

|    |                   |    |  |  |  |    |    |
|----|-------------------|----|--|--|--|----|----|
| 21 | IBV-13<br>(20-21) | 48 | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/48<br>DT.18-11-2020 | Iron & Steel Scrap Arising out of<br>Grounded BEML 28KL, WATER<br>TANKER OEM NO SL<br>NO.331/CIL NO.WS-193, DOC-<br>22.09.2009 Without Engine &<br>Transmission                              | Samaleswari<br>OCP, IB<br>Valley Area                  | MT | 30 |
| 22 | IBV-14<br>(20-21) | 49 | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/49<br>DT.18.11.2020 | Iron & Steel Scrap Arising out of<br>Grounded BD355 DOZER, OEM<br>NO SL NO10838/CIL NO.T-2185,<br>DOC-04.03.99 Without Engine &<br>Transmission  | Samaleswari<br>OCP, IB<br>Valley Area                  | MT | 30 |
| 23 | IBV-15<br>(20-21) | 50 | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/50<br>DT.18.11.2020 | Iron & Steel Scrap Arising out of<br>Grounded BD355 DOZER, OEM<br>NO SL NO11225/CIL NO.T-2822,<br>DOC-31.08.2008 Without Engine<br>& Transmission  | Samaleswari<br>OCP, IB<br>Valley Area                  | MT | 30 |
| 24 | IBV-16<br>(20-21) | 51 | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/51<br>DT.18.11.2020 | Iron & Steel Scrap Arising out of<br>Grounded BD355 DOZER, OEM<br>NO SL NO11147/CIL NO.T-2686,<br>DOC-02.05.2006 With Engine &<br>Transmission   | Samaleswari<br>OCP, IB<br>Valley Area                  | MT | 30 |
| 25 | IBV-17<br>(20-21) | 52 | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/52<br>DT.18.11.2020 | Iron & Steel Scrap Arising out of<br>Grounded BD355 DOZER, OEM<br>NO SL NO10878/CIL NO.T-2187,<br>DOC-09.04.1999 Without Engine<br>& Transmission  | Samaleswari<br>OCP, IB<br>Valley Area                  | MT | 30 |
| 26 | IBV-18<br>(20-21) | 53 | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/53<br>DT.18.11.2020 | Iron & Steel Scrap Arising out of<br>Grounded BD355 DOZER, OEM<br>NO SL NO10798/CIL NO.T-2189,<br>DOC-04.04.1999 With Engine &<br>Transmission   | Samaleswari<br>OCP, IB<br>Valley Area                  | MT | 30 |
| 27 | IBV-19<br>(20-21) | 54 | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/54<br>DT.27.11.2020 | Iron & Steel Scrap Arising out of<br>Grounded CAT834B WHEEL<br>DOZER, OEM NO SL NO-<br>7BR00678/CIL NO.T-2184, DOC-<br>02.07.1999 With Engine &<br>Without Transmission                      | Samaleswari<br>OCP, IB<br>Valley Area                  | MT | 30 |
| 28 | IBV-21<br>(20-21) | 56 | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/56<br>DT.27.11.2020 | Iron & Steel Scrap Arising out of<br>Grounded Tata Hitachi Hydraulic<br>Backhoe, OEM NO SL NO-<br>30010532/CIL NO.Exc-2251,<br>DOC-07.03.2003 With Engine &<br>Without Useful Sub Assemblies | Samaleswari<br>OCP, IB<br>Valley Area                  | MT | 30 |
| 29 | IBV-22<br>(20-21) | 57 | MCL/IBV/RSS/D<br>O/SURVEY<br>OFF/20-21/57<br>DT.10.12.2020 | Iron & Steel Scrap Arising out of<br>Grounded PROMTRACTOR<br>DOZER, OEM NO SL NO-<br>000240/CIL NO.T-3124, DOC-<br>03.07.2011 Without Engine &<br>Transmission                               | Samaleswari<br>OCP, IB<br>Valley Area                  | MT | 30 |
| 30 | IBV-24<br>(20-21) | 63 | MCL/SBP/EXCV<br>/2020/HEM-<br>8/2118<br>DT.06.11.2020      | Iron & Steel Scrap Arising out of<br>Grounded DOZER,CIL NO.T-3077<br>OEM NO SL NO-237 D.O.C-<br>29.06.2011 Without Engine &<br>Transmission  | At workshop<br>Area, Lajkura<br>OCP, IB<br>Valley Area | MT | 30 |

**LIST OF SCRAP LOTS FOR E-AUCTION NO. ASL/MCL/DISPOSAL/20-21/11**  
**DATED 04/02/2021**

|    |                   |    |   |   |  |    |    |
|----|-------------------|----|---|---|--|----|----|
| 31 | IBV-25<br>(20-21) | 62 | MCL/SBP/EXCV<br>/2019/HEM-8/927<br>DT.18.06.2020      | Iron & Steel Scrap Arising out of<br>Grounded Dill, CIL NO.RD-487<br>OEM NO SL NO-6010003 D.O.C-<br>17.08.2001 Without Major sub<br>Assy                  | At workshop<br>Area, Lajkura<br>OCP, IB<br>Valley Area | MT | 30 |
| 32 | IBV-26<br>(20-21) | 60 | MCL/SBP/EXCV<br>/2020/HEM-8/964<br>DT.25.06.2020      | Iron & Steel Scrap Arising out of<br>Grounded DOZER,CIL NO.T-3037<br>OEM NO -230 D.O.C-05.12.2010<br>Without Engine & Transmission                        | At workshop<br>Area, Lajkura<br>OCP, IB<br>Valley Area | MT | 30 |
| 33 | IBV-27<br>(20-21) | 59 | MCL/SBP/EXCV<br>/2019/HEM-8/08<br>DT.02.01.2019       | Iron & Steel Scrap Arising out of<br>Grounded DOZER,CIL NO.T-2865<br>OEM NO -11354 D.O.C-<br>20.03.2009 Without Engine &<br>Transmission                  | At workshop<br>Area, Lajkura<br>OCP, IB<br>Valley Area | MT | 25 |
| 34 | IBV-28<br>(20-21) | 58 | MCL/SBP/EXCV<br>/2015/HEM-<br>8/2237<br>DT.23.11.2015 | Iron & Steel Scrap Arising out of<br>Grounded Dozer, CIL NO.T-2713<br>OEM NO -11102 D.O.C-<br>03.05.2005 Without Engine &<br>Transmission                 | At workshop<br>Area, Lajkura<br>OCP, IB<br>Valley Area | MT | 27 |
| 35 | IBV-29<br>(20-21) | 64 | MCL/SBP/EXCV<br>/2020/HEM-8/305<br>DT.25.02.2020      | Iron & Steel Scrap Arising out of<br>Grounded Excavator H55N<br>Demag, CIL NO.Exc-2579 OEM<br>NO -55007 D.O.C-10.04.2009<br>Without Engine & Transmission | At workshop<br>Area, Lajkura<br>OCP, IB<br>Valley Area | MT | 20 |
| 36 | IBV-30<br>(20-21) | 61 | MCL/SBP/EXCV<br>/2020/HEM-8/305<br>DT.25.02.2020      | Iron & Steel Scrap Arising out of<br>Grounded Excavator H55N<br>Demag, CIL NO.Exc-2573 OEM<br>NO -55008 D.O.C-20.04.2009<br>Without Engine & Transmission | At workshop<br>Area, Lajkura<br>OCP, IB<br>Valley Area | MT | 20 |