

LIST OF SCRAP LOTS FOR E-AUCTION NO. ASL/MCL/DISPOSAL/19-20/21
DATED 27/01/2020

Sl No	MCL Control no.	Survey off Report no	Material description	Location	UOM	QTY
1	HIN-07 (19-20)	DO/RS- HA/19-20/09 dt.18.07.19	Old & Used Un-serviceable Iron Scrap	Field ESC, Balaram OCP, Hingula Area	MT	50
2	HIN-11 (19-20)	DO/RS- HA/19-20/14 Dt.27/09/19	Scrap old and used unserviceable Iron	Field Workshop, Hingula Area	MT	50
3	HIN-12 (19-20)	DO/RS- HA/19-20/13 Dt.27/09/19	Scrap old and used unserviceable Iron	Units store, BOCP, Hingula Area	MT	12
4	IBV-09 (19-20)	MCL/IBV/RS S/DO/Survey Off/19-20/21 Dt.06/08/19	Scrap old used & Unserviceable Old Drill Bit 6 1/4"	Regional store Ib-Valley Area	Nos	165
5	IBV-10 (19-20)	MCL/IBV/RS S/DO/Survey Off/19-20/23 Dt.06/08/19	Scrap Old used & Unserviceable Old Drill Bit 10 5/8"	Regional store Ib-Valley Area	Nos	6
6	IBV-16 (19-20)	MCL/IBV/RS S/DO/Survey Off/19-20/22 Dt.06/08/19	Scrap Old used & Unserviceable Old Drill Bit 9 7/8"	Regional store Ib-Valley Area	Nos	31
7	LIN-06 (19-20)	GM/LA/RS/ MMD/Scrap/ SOR/19- 20/200 dt.05.09.19	Scrap arising out of Old used, Damaged & Un-Serviceable C.I Pipe (Dia 24"X6 Mtr. Length)	IWSS, Lingaraj Area	MT	40
8	LIN-07 (19-20)	GM/LA/RS/ MMD/Scrap/ SOR/19- 20/201 dt.05.09.19	Scrap arising out of Old used, Damaged & Un-Serviceable C.I Scrap of different sizes pump spares Sluice-Valves etc.	IWSS, Lingaraj Area	MT	10

9	HIN-18 (19-20)	DO/RS- HA/19-20/20 Dt.22/10/19	Scrap Old Used Unserviceable Drill Bit Size 9 7/8"	Unit store, Balaram OCP, Hingula Area	Nos	250
10	HIN-19 (19-20)	DO/RS- HA/19-20/21 Dt.22/10/19	Scrap Old Used Unserviceable Drill Bit Size 6 1/4"	Unit store, Balaram OCP, Hingula Area	Nos	300
11	LKP-20 (19-20)	MCL/LKPA/ Lilari OCP /US/19-20/05 Dt.29/07/19	Mis scrap arising out of old used unserviceable Iron, steel of various HEMM & Spares	Excavation Workshop, Lilari OCP, Lakhanpur Area	MT	100
12	LKP-21 (19-20)	MCL/LKPA/ Lilari OCP / US/19-20/06 Dt.29/07/19	Mis scrap arising out of old used unserviceable Iron, steel of various HEMM & Spares	Excavation Workshop, Lilari OCP, Lakhanpur Area	MT	200
13	LKP-22 (19-20)	MCL/LKPA/ LKP.OCP/US /18-19/35 Dt.22/06/18	Mis scrap arising out of old used unserviceable Iron, steel of various HEMM & Spares	Unit Store, LKP OCP, Lakhanpur Area	MT	20
14	JGN-04 (19-20)	4741/RS(JA)/ S.Off/19- 20/48 Dt.09/06/19	Scrap Old Used unserviceable Drill Bit 6 1/4"	Ananta OCP Colliery Store Jagannath Area	Nos	403
15	JGN-05 (19-20)	4741/RS(JA)/ S.Off/19- 20/47 Dt.09/06/19	Scrap Old Used unserviceable Drill Bit 9 7/8"	Ananta OCP Colliery Store Jagannath Area	Nos	51
16	JGN-06 (19-20)	4741/RS(JA)/ S.Off/19- 20/50 Dt.09/06/19	Scrap Old Used unserviceable PB/GM Bush washer pad, etc.	Ananta OCP Colliery Store Jagannath Area	KG	820
17	JGN-14 (19-20)	4741/RS(JA)/ S.Off/19- 20/49 Dt.09/06/19	Scrap arising out from old, used & unserviceable spare parts of Drill, EKG Shovel, Hyd Excavators, Dozers etc.	Excavation workshop Jagannath Colliery Jagannath Area	MT	20
18	HIN-24 (19-20)	DO/RS- HA/19-20/26 Dt.05/12/19	Scrap arising out of Old & Used Unserviceable RECP-750E Drill, OEM SI no.6019501/CIL no.RDC396 without Main Motor & Compressor	Field workshop, BOCP, Hingula Area	MT	10

19	HIN-25 (19-20)	DO/RS- HA/19-20/27 Dt.05/12/19	Scrap arising out of Old & Used Unserviceable Deregistered ESCORT 8T CRANE OEM Sl no.1129/CIL No.MC-139 without Engine	Excavation workshop, BOCP, Hingula Area	MT	3.5
20	HIN-26 (19-20)	DO/RS- HA/19-20/28 Dt.05/12/19	Scrap arising out of Old & Used Unserviceable IDM-70E DRILL OEM no.9210061/CIL No.RDC359, without Motor & Compressor	Field workshop, BOCP, Hingula Area	MT	13
21	HIN-21 (19-20)	DO/HA/19- 20/22 Dt.07.11.19	Scrap Old & Unserviceable deregistered Maruti Udyog Gypsy Regd.no.OR 06 4107	Regional Store, Hingula Area	Nos	1
22	HIN-20 (19-20)	DO/HA/19- 20/23 Dt.21.09.19	Scrap BH-210M deregistered Dumper without engine & without transmission OEM No.D8095, Engine SL no.25234907 Transmission Sl no.31601930 & without tyre	Inside HSD filling station workshop of BOCP, Hingula Area	MT	25
23	HIN-08 (19-20)	DO/RS- HA/19-20/08 dt.18.07.19	Scrap arising out of D355 Dozer Sl.no.G-11300, CIL No.T-2857 along with identified sub- assemblies, i.e blade asy, chasis etc and without engine & transmission	Field ESC, Balaram OCP, Hingula Area	MT	20
24	HIN-09 (19-20)	DO/RS- HA/19-20/11 dt.18.07.19	Scrap Old used & Unserviceable deregistered Fire Tender, Regd no.OR-19B7804, Chassis No.;JWE539709, Engine No- JWE402776, Model-2004	Hingula Open Cast Project, Hingula Area	Nos	1
25	HIN-16 (19-20)	DO/RS- HA/19-20/18 Dt.15.10.19	Scrap Old & Used Unserviceable deregistered Ambassador Car Regd No.OR06 7341, Engine No:-AGV743895, Chassis No.CEDGVI50597	Regional Store, Hingula Area	Nos	1
26	HIN-22 (19-20)	DO/RS- HA/19-20/24 Dt.13/11/19	Old Used & Unserviceable Scrap Iron materials	Near Excavation workshop, Hingula OCP, Hingula Area	MT	50

27	CWS(IB V)-01 (19-20)	MCL/GM/C WS/IBV/RS/S urvey Off/19- 20/01 Dt.25/11/19	Old Used Un-serviceable Iron & Steel scrap arising out of HEMM spares etc.	Work shop premises, CWS IB-Valley	MT	80
28	CWS(IB V)-02 (19-20)	MCL/GM/C WS/IBV/RS/S urvey Off/19- 20/02 Dt.04/12/19	Scrap arising out of Old & Used Unserviceable deregistered TATA Truck Regd.no.OR-23- 0957, Engine no.497SPTC31LX Z904267, Chassis no.357124LXZ818087	Workshop Premises, CWS IBV	Nos	1
29	CWS(IB V)-03 (19-20)	MCL/GM/C WS/IBV/RS/S urvey Off/19- 20/03 Dt.04/12/19	Scrap arising out of Old & Used Unserviceable deregistered TATA Mini Truck Regd.no.OR- 15A 4717, Engine no.497SP21613370, Chassis no.357010844709	Workshop Premises, CWS IBV	Nos	1
30	CWS(IB V)-04 (19-20)	MCL/GM/C WS/IBV/RS/S urvey Off/19- 20/04 Dt.04/12/19	Scrap arising out of Old & Used Unserviceable deregistered Maruti Omini Ambulance Regd.no.OR15C-8853, Engine no.F88IN1728959, Chassis No.ST911N278162	Workshop Premises, CWS IB-Valley	Nos	1
31	LKP-47 (19-20)	MCL/LKP/L KP.OCP/EXC V/75 Dt.04/09/19	Scrap arising out of REAR DUMPER model-HM-1035 Make: HM LTD OEM No.10350735, CIL No.D-5685 with Engine Assy & Transmission Assy without Batteries, self starter, alternator, tyres and other servicable sub- assys	Lakhanpur OCP, Lakhanpur Area	MT	10
32	LKP-48 (19-20)	MCL/LKP/L KP.OCP/EXC V/US/ 76 Dt.04/09/19	Scrap arising out of REAR DUMPER model-HM-1035 Make: HM LTD OEM No.10350732, CIL No.D-5682 with Engine Assy & Transmission Assy without Batteries, self starter, alternator, tyres and other servicable sub- assys	Lakhanpur OCP, Lakhanpur Area	MT	9

33	LKP-49 (19-20)	MCL/LKP/L KP.OCP/EXC V/US/ 77 Dt.04/09/19	Scrap arising out of REAR DUMPER model-HM-1035 Make: HM LTD OEM No.10350912, CIL No.D-6059 with Engine Assy & Transmission Assy without Batteries, self starter, alternator, tyres and other servicable sub- assys	Lakhanpur OCP, Lakhanpur Area	MT	10
34	LKP-50 (19-20)	MCL/LKPA/ Lilari OCP/US/19- 20/07 Dt.16/11/19	Misc Scrap arising out of Old Used, Unserviceable Iron & Steel of various HEMM & Spares	Excavation Workshop, Lilari OCP, Lakhanpur Area	MT	200
35	JGN-17 (19-20)	4741/RS/JA/S -Off/19-20/72 Dt.04/11/19	Old used unserviceable Scrap Iron & Steel (HEMM Spares etc)	Regional Store Jagannath Area	MT	50
36	IBV-17 (19-20)	MCL/IBV/RS S/ DO/Survey Off/19-20/29 Dt.19.11.19	Scrap 160mm Drill M/C Model- 650 RECP 650 OEM Sl.no.6029602, CIL No.RDC- 713 (Iron and steel scrap arising out of grounded drill machine)	SOCP, IB- Valley Area	MT	20
37	IBV-18 (19-20)	MCL/IBV/RS S/ DO/Survey Off/19-20/30 Dt.19.11.19	Scrap 160mm Drill M/C Model- 650 RECP 650 OEM Sl.no.6029407, CIL No.RDC- 688 (Iron and steel scrap arising out of grounded drill machine)	SOCP, IB- Valley Area	MT	20
38	IBV-19 (19-20)	MCL/IBV/RS S/ DO/Survey Off/19-20/31 Dt.19.11.19	Scrap 160mm Drill M/C Model- 650 RECP 650 OEM Sl.no.6029317, CIL No.RDC- 656 (Iron and steel scrap arising out of grounded drill machine)	SOCP, IB- Valley Area	MT	20
39	IBV-20 (19-20)	MCL/IBV/RS S/ DO/Survey Off/19-20/32 Dt.19.11.19	Scrap 160mm Drill M/C Model- 650 Model- ROTACOAL OEM Sl.no.9106385, CIL No.RDC- 478 (Iron and steel scrap arising out of grounded drill machine)	SOCP, IB- Valley Area	MT	20
40	IBV-21 (19-20)	MCL/IBV/RS S/ DO/Survey Off/19-20/33 Dt.19.11.19	Scrap deregistered 10T DASS JONES CRANE, OEM Sl.no.213/CIL No.MC-388, DOC-16.02.1996	SOCP, IB- Valley Area	MT	30

41	IBV-22 (19-20)	MCL/IBV/RS S/DO/Survey Off/19-20/34 Dt.19.11.19	Scrap deregistered CAT16H Motor Grader M/C no.6ZJ00525, CIL No.G-288, D.O.C-02.07.99	SOCP, IB- Valley Area	MT	20
42	LKP-28 (19-20)	MCL/GM/LK PA/SOR/19- 20/27 Dt.05/11/19	Scrap arising out of deregistered Omini Van having Regd.no.OR- 15A-2557, Engine no.741299, Chasis No.907353	Regional /Central store, Belpahar, Lakhanpur Area	Nos	1
43	LKP-29 (19-20)	MCL/GM/LK PA/SOR/19- 20/28 Dt.05/11/19	Scrap arising out of deregistered Ambassador Car having Regd.no.OR-51A-4812, Engine no.III 666093 Chassis No.6EH098297	Regional /Central store, Belpahar, Lakhanpur Area	Nos	1
44	LKP-30 (19-20)	MCL/GM/LK PA/SOR/19- 20/29 Dt.05/11/19	Scrap arising out of deregistered Mahendra Jeep having Regd.no.OSD-5790, Engine no.DN33906, Chassis no.DN33906	Regional /Central store, Belpahar, Lakhanpur Area	Nos	1
45	LKP-31 (19-20)	MCL/GM/LK PA/SOR/19- 20/30 Dt.05/11/19	Scrap arising out of deregistered Mahendra Jeep having Regd.no.OR-15A-5002, Engine noMM540DP4D, R03283 Chassis no.DR03283	Regional /Central store, Belpahar, Lakhanpur Area	Nos	1
46	LKP-32 (19-20)	MCL/GM/LK PA/SOR/19- 20/31 Dt.05/11/19	Scrap arising out of deregistered Maruti Gypsy having Regd.no.ORW-0388, Engine no.122515, Chassis no.125218	Regional /Central store, Belpahar, Lakhanpur Area	Nos	1
47	LKP-33 (19-20)	MCL/GM/LK PA/SOR/19- 20/32 Dt.05/11/19	Scrap arising out of deregistered Omini Van having Regd.no.OR- 15A-4761, Engine no.F8BIN795230, Chassis No.ST911N922260	Regional /Central store, Belpahar, Lakhanpur Area	Nos	1